



IRIS CONTRACT HIGHWAY INSPECTIONS



INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

60670 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 26/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 26/04/2023 09:39:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 26/04/2023

60649 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 25/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 25/04/2023 14:56:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 25/04/2023

60615 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 24/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 24/04/2023 08:27:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 24/04/2023

60592 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 23/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 22/04/2023 10:00:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 22/04/2023

60580 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 22/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 22/04/2023 10:00:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 22/04/2023

60568 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 21/04/2023**



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 21/04/2023 08:14:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 21/04/2023

60554 **SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 20/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 20/04/2023 08:48:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 20/04/2023

Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 20/04/2023 08:47:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 20/04/2023

60544 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 19/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 18/04/2023 12:50:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 18/04/2023

60530 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 18/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 18/04/2023 12:50:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 18/04/2023

60501 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 17/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 17/04/2023 07:49:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 17/04/2023



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO	INSPECTION DESCRIPTION		
60479	SWTRA Safety Patrol of M4 J36_J49 Patrol on 16/04/2023		
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB		Inspection Date: 16/04/2023 08:25:00	
WEATHER: Fine	SURFACE CONDITION: DRY	INSPECTOR:p.v.evans	SURVEY METHOD: DRIVEN
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 16/04/2023			
60467	SWTRA Safety Patrol of M4 J36_J49 Patrol on 15/04/2023		
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB		Inspection Date: 15/04/2023 08:39:00	
WEATHER: Fine	SURFACE CONDITION: DRY	INSPECTOR:p.v.evans	SURVEY METHOD: DRIVEN
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 15/04/2023			
60455	SWTRA Safety Patrol of M4 J36_J49 Patrol on 14/04/2023		
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB		Inspection Date: 14/04/2023 08:22:00	
WEATHER: Fine	SURFACE CONDITION: DRY	INSPECTOR:p.v.evans	SURVEY METHOD: DRIVEN
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 14/04/2023			
60438	SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 13/04/2023		
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB		Inspection Date: 13/04/2023 08:12:00	
WEATHER: Fine	SURFACE CONDITION: DRY	INSPECTOR:p.v.evans	SURVEY METHOD: DRIVEN
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 13/04/2023			
Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB		Inspection Date: 13/04/2023 09:24:00	
WEATHER: Fine	SURFACE CONDITION: DRY	INSPECTOR:p.v.evans	SURVEY METHOD: DRIVEN
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 13/04/2023			
60409	SWTRA Safety Patrol of M4 J36_J49 Patrol on 12/04/2023		
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB		Inspection Date: 12/04/2023 15:43:00	
WEATHER: Raining	SURFACE CONDITION: WET	INSPECTOR:p.v.evans	SURVEY METHOD: DRIVEN



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 12/04/2023

60376 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 11/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 11/04/2023 09:33:00

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 11/04/2023

60323 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 10/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 08/04/2023 10:40:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 08/04/2023

60278 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 09/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 09/04/2023 10:40:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 09/04/2023

60242 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 08/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 08/04/2023 08:33:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 08/04/2023

60230 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 07/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 07/04/2023 08:17:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 07/04/2023

60217 **SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 06/04/2023**



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 06/04/2023 08:11:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 06/04/2023

Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 06/04/2023 11:50:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 06/04/2023

60205 SWTRA Safety Patrol of M4 J36_J49 Patrol on 05/04/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 05/04/2023 08:17:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 05/04/2023

60187 SWTRA Safety Patrol of M4 J36_J49 Patrol on 04/04/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 04/04/2023 11:43:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 04/04/2023

60152 SWTRA Safety Patrol of M4 J36_J49 Patrol on 03/04/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 03/04/2023 08:08:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 03/04/2023

60127 SWTRA Safety Patrol of M4 J36_J49 Patrol on 02/04/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 02/04/2023 10:31:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 02/04/2023



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

60113 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 01/04/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 01/04/2023 08:22:00

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 01/04/2023

60100 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 31/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 31/03/2023 08:51:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 31/03/2023

60086 **SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 30/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 30/03/2023 09:04:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 30/03/2023

Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB

Inspection Date: 30/03/2023 13:48:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 30/03/2023

60073 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 29/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 29/03/2023 08:39:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 29/03/2023

60049 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 28/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 28/03/2023 08:33:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 28/03/2023

60019 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 27/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 27/03/2023 10:47:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 27/03/2023

59992 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 26/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 26/03/2023 10:08:00

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 26/03/2023

59980 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 25/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 25/03/2023 10:08:00

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 25/03/2023

59968 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 24/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 24/03/2023 08:45:17

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 24/03/2023

59954 **SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 23/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 23/03/2023 08:42:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:Richard V

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 23/03/2023



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:Richard V

Inspection Date: 23/03/2023 08:42:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 23/03/2023

59944 SWTRA Safety Patrol of M4 J36_J49 Patrol on 22/03/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 22/03/2023 14:38:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 22/03/2023

59932 SWTRA Safety Patrol of M4 J36_J49 Patrol on 21/03/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 21/03/2023 08:12:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 21/03/2023

59907 SWTRA Safety Patrol of M4 J36_J49 Patrol on 20/03/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 20/03/2023 10:44:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 20/03/2023

59882 SWTRA Safety Patrol of M4 J36_J49 Patrol on 19/03/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 19/03/2023 08:27:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 19/03/2023

59870 SWTRA Safety Patrol of M4 J36_J49 Patrol on 18/03/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 18/03/2023 09:15:00

SURVEY METHOD: DRIVEN



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 18/03/2023

59859 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 17/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 17/03/2023 11:47:14

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 17/03/2023

59848 **SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 16/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 16/03/2023 08:42:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 16/03/2023

Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 16/03/2023 12:43:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 16/03/2023

59837 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 15/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 15/03/2023 08:42:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 15/03/2023

59827 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 14/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 14/03/2023 08:53:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 14/03/2023

59801 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 13/03/2023**



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 13/03/2023 08:09:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 13/03/2023

59776 SWTRA Safety Patrol of M4 J36_J49 Patrol on 12/03/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 12/03/2023 08:28:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 12/03/2023

59764 SWTRA Safety Patrol of M4 J36_J49 Patrol on 11/03/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 11/03/2023 08:29:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 11/03/2023

59752 SWTRA Safety Patrol of M4 J36_J49 Patrol on 10/03/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 10/03/2023 10:14:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 10/03/2023

59738 SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 09/03/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 08/03/2023 09:32:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 08/03/2023

Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 08/03/2023 09:32:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 08/03/2023



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

59724 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 08/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 08/03/2023 09:32:00

WEATHER: Snow

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 08/03/2023

59706 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 07/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 07/03/2023 08:24:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 07/03/2023

59678 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 06/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 06/03/2023 08:42:18

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 06/03/2023

59650 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 05/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 05/03/2023 10:38:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:Coryton.r

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 05/03/2023

59637 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 04/03/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 04/03/2023 08:43:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 04/03/2023

59626 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 03/03/2023**



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 03/03/2023 15:20:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 03/03/2023

59614 SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 02/03/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 02/03/2023 15:20:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 02/03/2023

Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 02/03/2023 15:20:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 02/03/2023

59601 SWTRA Safety Patrol of M4 J36_J49 Patrol on 01/03/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 01/03/2023 09:16:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 01/03/2023

59577 SWTRA Safety Patrol of M4 J36_J49 Patrol on 28/02/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 28/02/2023 11:57:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 28/02/2023

59547 SWTRA Safety Patrol of M4 J36_J49 Patrol on 27/02/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 27/02/2023 09:29:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 27/02/2023



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO	INSPECTION DESCRIPTION			
59520	SWTRA Safety Patrol of M4 J36_J49 Patrol on 26/02/2023			
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB			Inspection Date: 26/02/2023 09:02:00	
WEATHER: Fine	SURFACE CONDITION: DRY	INSPECTOR:p.v.evans	SURVEY METHOD: DRIVEN	
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 26/02/2023				
59508	SWTRA Safety Patrol of M4 J36_J49 Patrol on 25/02/2023			
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB			Inspection Date: 25/02/2023 08:29:00	
WEATHER: Fine	SURFACE CONDITION: DRY	INSPECTOR:p.v.evans	SURVEY METHOD: DRIVEN	
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 25/02/2023				
59496	SWTRA Safety Patrol of M4 J36_J49 Patrol on 24/02/2023			
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB			Inspection Date: 24/02/2023 10:57:00	
WEATHER: Fine	SURFACE CONDITION: DRY	INSPECTOR:p.v.evans	SURVEY METHOD: DRIVEN	
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 24/02/2023				
59479	SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 23/02/2023			
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB			Inspection Date: 23/02/2023 11:10:00	
WEATHER: Fine	SURFACE CONDITION: WET	INSPECTOR:p.v.evans	SURVEY METHOD: DRIVEN	
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 23/02/2023				
Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB			Inspection Date: 23/02/2023 11:10:00	
WEATHER: Fine	SURFACE CONDITION: WET	INSPECTOR:p.v.evans	SURVEY METHOD: DRIVEN	
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 23/02/2023				
59468	SWTRA Safety Patrol of M4 J36_J49 Patrol on 22/02/2023			
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB			Inspection Date: 22/02/2023 08:37:00	
WEATHER: Fine	SURFACE CONDITION: WET	INSPECTOR:p.v.evans	SURVEY METHOD: DRIVEN	



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 22/02/2023

59456 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 21/02/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 21/02/2023 09:31:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 21/02/2023

59431 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 20/02/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 20/02/2023 08:42:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 20/02/2023

59406 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 19/02/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 19/02/2023 08:20:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 19/02/2023

59394 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 18/02/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 18/02/2023 08:15:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 18/02/2023

59383 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 17/02/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 17/02/2023 08:37:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 17/02/2023

59372 **SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 16/02/2023**



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 16/02/2023 08:29:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 16/02/2023

Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 16/02/2023 12:12:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 16/02/2023

59361 SWTRA Safety Patrol of M4 J36_J49 Patrol on 15/02/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 15/02/2023 08:13:07

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 15/02/2023

59351 SWTRA Safety Patrol of M4 J36_J49 Patrol on 14/02/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 14/02/2023 14:19:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 14/02/2023

59325 SWTRA Safety Patrol of M4 J36_J49 Patrol on 13/02/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 13/02/2023 08:02:11

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 13/02/2023

59300 SWTRA Safety Patrol of M4 J36_J49 Patrol on 12/02/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 12/02/2023 06:59:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 12/02/2023



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

59288 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 11/02/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 11/02/2023 08:02:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 11/02/2023

59276 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 10/02/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 10/02/2023 08:16:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 10/02/2023

59268 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 08/02/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 08/02/2023 09:07:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:Coryton.r

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 08/02/2023

59261 **SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 09/02/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 09/02/2023 08:29:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 09/02/2023

Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB

Inspection Date: 09/02/2023 18:44:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 09/02/2023

59251 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 07/02/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 06/02/2023 09:26:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

**BATCH
NO** **INSPECTION DESCRIPTION**

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 06/02/2023

59245 SWTRA Safety Patrol of M4 J36_J49 Patrol on 08/02/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 08/02/2023 11:44:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 08/02/2023

59230 SWTRA Safety Patrol of M4 J36_J49 Patrol on 06/02/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 06/02/2023 09:26:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 06/02/2023

59226 SWTRA Safety Patrol of M4 J36_J49 Patrol on 07/02/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 07/02/2023 07:25:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 07/02/2023

59203 SWTRA Safety Patrol of M4 J36_J49 Patrol on 05/02/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 05/02/2023 07:07:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 05/02/2023

59175 SWTRA Safety Patrol of M4 J36_J49 Patrol on 04/02/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 04/02/2023 00:00:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 04/02/2023

59164 SWTRA Safety Patrol of M4 J36_J49 Patrol on 03/02/2023



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 03/02/2023 08:54:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 03/02/2023

59147 SWTRA Safety Patrol of M4 J36_J49 Patrol on 01/02/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 01/02/2023 16:00:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 01/02/2023

59132 SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 02/02/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 02/02/2023 08:28:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 02/02/2023

Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 02/02/2023 12:57:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 02/02/2023

59124 SWTRA Safety Patrol of M4 J36_J49 Patrol on 31/01/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

Inspection Date: 31/01/2023 08:44:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 31/01/2023

59097 SWTRA Safety Patrol of M4 J36_J49 Patrol on 30/01/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 30/01/2023 07:03:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 30/01/2023



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO	INSPECTION DESCRIPTION
59074	SWTRA Safety Patrol of M4 J36_J49 Patrol on 29/01/2023
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB	
WEATHER: Raining	SURFACE CONDITION: WET
INSPECTOR:p.v.evans	INSPECTION DATE: 29/01/2023 08:39:00
SURVEY METHOD: DRIVEN	
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 29/01/2023	
59053	SWTRA Safety Patrol of M4 J36_J49 Patrol on 28/01/2023
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB	
WEATHER: Fine	SURFACE CONDITION: DRY
INSPECTOR:p.v.evans	INSPECTION DATE: 28/01/2023 14:43:00
SURVEY METHOD: DRIVEN	
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 28/01/2023	
59041	SWTRA Safety Patrol of M4 J36_J49 Patrol on 27/01/2023
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB	
WEATHER: Fine	SURFACE CONDITION: DRY
INSPECTOR:p.v.evans	INSPECTION DATE: 27/01/2023 08:39:00
SURVEY METHOD: DRIVEN	
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 27/01/2023	
59009	SWTRA Safety Patrol of M4 J36_J49 Patrol on 25/01/2023
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB	
WEATHER: Fine	SURFACE CONDITION: DRY
INSPECTOR:p.v.evans	INSPECTION DATE: 25/01/2023 08:32:00
SURVEY METHOD: DRIVEN	
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 25/01/2023	
59003	SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 26/01/2023
Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB	
WEATHER: Fine	SURFACE CONDITION: DRY
INSPECTOR:p.v.evans	INSPECTION DATE: 26/01/2023 08:23:00
SURVEY METHOD: DRIVEN	
NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 26/01/2023	
Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB	
WEATHER: Fine	SURFACE CONDITION: DRY
INSPECTOR:p.v.evans	INSPECTION DATE: 26/01/2023 09:49:00
SURVEY METHOD: DRIVEN	



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 26/01/2023

58993 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 24/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 24/01/2023 08:31:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 24/01/2023

58981 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 23/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 23/01/2023 18:41:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 23/01/2023

58962 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 22/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 22/01/2023 13:47:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 22/01/2023

58943 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 21/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 21/01/2023 11:33:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 21/01/2023

58930 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 20/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 20/01/2023 08:57:00

WEATHER: Fine

SURFACE CONDITION: ICE

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 20/01/2023

58906 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 18/01/2023**



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Snow

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 18/01/2023 08:30:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 18/01/2023

58900 SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 19/01/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Snow

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 19/01/2023 08:40:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 19/01/2023

Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB

WEATHER: Fine

SURFACE CONDITION: ICE

INSPECTOR:p.v.evans

Inspection Date: 19/01/2023 15:37:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 19/01/2023

58894 SWTRA Safety Patrol of M4 J36_J49 Patrol on 17/01/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 17/01/2023 08:32:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 17/01/2023

58882 SWTRA Safety Patrol of M4 J36_J49 Patrol on 16/01/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 16/01/2023 09:05:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 16/01/2023

58862 SWTRA Safety Patrol of M4 J36_J49 Patrol on 15/01/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 15/01/2023 09:29:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 15/01/2023



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

58843 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 14/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 14/01/2023 13:52:07

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 14/01/2023

58830 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 13/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 13/01/2023 14:05:00

WEATHER: Fine

SURFACE CONDITION: DRY

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 13/01/2023

58806 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 11/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 11/01/2023 09:22:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 11/01/2023

58800 **SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 12/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 12/01/2023 13:26:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

[WFE-23296109](#)

CATEGORY 1, SAFETY FENCE, ACCIDENT DAMAGE - Verge barrier damage following RTC - 3 Posts and 3 SSTCB

Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB

Inspection Date: 12/01/2023 13:26:00

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 12/01/2023

58792 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 10/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

Inspection Date: 10/01/2023 08:26:00

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

SURVEY METHOD: DRIVEN



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 10/01/2023

58773 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 09/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 09/01/2023 08:30:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 09/01/2023

58751 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 08/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 08/01/2023 08:23:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 08/01/2023

58729 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 07/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 07/01/2023 08:43:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 07/01/2023

58717 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 06/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 06/01/2023 09:13:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 06/01/2023

58693 **SWTRA Safety Patrol of M4 J36_J49 Patrol on 04/01/2023**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 04/01/2023 15:25:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 04/01/2023

58687 **SWTRA Safety Inspection (7 day) of M4 J36_J49 Safety on 05/01/2023**



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 05/01/2023 08:59:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 05/01/2023

Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 05/01/2023 14:32:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 05/01/2023

58679 SWTRA Safety Patrol of M4 J36_J49 Patrol on 03/01/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 03/01/2023 13:43:39

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 03/01/2023

58655 SWTRA Safety Patrol of M4 J36_J49 Patrol on 02/01/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 02/01/2023 09:27:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 02/01/2023

58632 SWTRA Safety Patrol of M4 J36_J49 Patrol on 01/01/2023

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR:p.v.evans

Inspection Date: 01/01/2023 09:20:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 01/01/2023

57695 SSI : Detailed Inspection - Road Studs: Conspicuity of M4 Central Detailed on 02/11/2

Link/Section: - M4, 1000484080 - END SLIP ON J47 - START SLIP OFF J46 EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:g.morris

Inspection Date: 12/01/2023 20:15:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 12/01/2023



IRIS CONTRACT HIGHWAY INSPECTIONS

INSPECTIONS BY ROUTE & DEFECTS LOGGED

BATCH NO **INSPECTION DESCRIPTION**

Link/Section: - M4, 1000484096 - START SLIP ON J47 - END SLIP ON EB

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR:g.morris@

Inspection Date: 12/01/2023 22:07:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 12/01/2023